


## PRODUCT BULLETIN JSK 37U"W" Topplate Liner Update

## **Effective October 2009**

Jost International announces the availability of an improved low lube liner.

The new liner is reinforced with a bonded steel backing plate.



- > Field tests have revealed significant improvements in durability under frequent coupling conditions.
- > This product improvement will be a running change

## -No part numbers change-

> After October 1<sup>st</sup> <u>ALL</u> Low Lube Fifth Wheels <u>WILL BE</u> supplied with the new Reinforced Low Lube Liners.

If you have any questions contact Jost's customer service at (800) 253-5105.

The right to alter specifications is reserved.

